

Technical drawing of a mechanical part showing top and side views. Dimensions include A, B, C1, C2, D1, D2, E, and F. Surface finish symbols are indicated: P0.6, P0.5, 2-R2, 4-R0.8, and C0.2 ref.

[illegible]